

Floating Leveling Head Bearing

SWIFT FUTURA

Technical Support Field Bulletin

Date: 3/01/01

To: CEC Clients

From: Peter Novak


Subject: Floating Level Heads

Bulletin: No. 21

It has been brought to our attention that there is a possibility of a defect with the Floating Leveling Head. The concern is that the bearing is binding preventing free horizontal movement as well as the leveling head not being parallel with the mounting rail and kindroff bracket.

Enclosed is a picture showing how to detect if your leveling unit needs to be sent to CEC for modification. Move the leveling head flush against the mounting bracket. The leveling head should be parallel with the mounting bracket and there should be no gap.

If you have a Leveling unit that is not free floating or with a gap, please contact Joe Cali at 201-508-2320 for an RMA number and send it to us UPS collect. It will be modified and returned within 24 hours.



Yours truly,

Peter Novak

V.P. Engineering

Technical Support: **201-508-2300**

Fax: **201-508-2250**